VIKING PAINTS INC

TE-2501 FAST SET CATALYST PART-B FOR USE WITH ALL FAST SET PART-A

Date Printed: 3/17/2016

Date Revised: Page 1 of 8

1. Product and Company Identification

Product Name : TE-2501 FAST SET CATALYST PART-B

Product Code : VPE-107-FAST SET

Recommended Use: Filling cracks in concrete.

Company Identification:

VIKING PAINTS INC 100 W 78TH ST

RICHFIELD MN, 55423

Information Phone: 612-866-1212

Emergency Phone: 1-800-535-5053 24HRS

2. Hazards Identification

2.1 Classification of the substance or mixture GHS-US classification

Corrosive Liquid Category 1 H290 Skin Corrosion/Irritation Category 2 H315 Sensitization - Skin Category 1 H317 Causes serious eye damage Category 1 H318 Acute Toxicity - Inhalation Category 4 H332 Carcinogenicity Category 2 H351

2.2 Label elements

Symbols

Corrosive, Exclamation, Heath Hazard

Hazard pictograms







Signal word (GHS-US): Warning

Hazard statements (GHS-US)

H290 - May be corrosive to metals.

H315 - Causes skin irritation

H317 - May cause an allergic skin reaction

H319 - Causes serious eye irritation

H332 - Harmful if inhaled

H351 - Suspected of causing cancer

Precautionary statements

P201 - Obtain special instructions before use

P202 - Do not handle until all safety precautions have been read and understood

VIKING PAINTS INC

TE-2501 FAST SET CATALYST PART-B FOR USE WITH ALL FAST SET PART-A

Date Printed: 3/17/2016

Date Revised: Page 2 of 8

- P210 Keep away from heat, sparks, and open flames No smoking
- P233 Keep container tightly closed
- P261 Avoid breathing fume, mist, vapours, and spray
- P264 Wash hands, forearms and face after handling
- P271 Use only outdoors or in a well-ventilated area
- P272 Contaminated work clothing should not be allowed out of the workplace
- P280 Wear protective gloves, eye protection, and protective clothing
- P281 Use personal protective equipment as required
- P302 + P352 IF ON SKIN: Wash with plenty of soap and water
- P303 + P361 + P353 IF ON SKIN (or hair): Remove immediately all contaminated clothing. Rinse skin with water.
- P304 + P340 IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing
- P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P308 + P313 IF exposed or concerned: Get medical advice/attention
- P312 Call a POISON CENTER or doctor if you feel unwell
- P321 Specific treatment (See first aid instructions on this label)
- P333 + P313 If skin irritation or rash occurs: Get medical advice/attention
- P337 + P313 If eye irritation persists: Get medical advice/attention
- P362 Take off contaminated clothing and wash before reuse
- P370 + P378 In case of fire: Use foam, CO2, and dry extinguishing powder for extinction
- P406 Store in corrosion resistant container.
- P403 + P235 Store in a well-ventilated place. Keep cool.
- P405 Store locked upN/A
- P501 Dispose of contents/container to a licensed hazardous-waste disposal contractor or collection site except for empty clean containers which can be disposed of as non-hazardous waste

3. Composition/Information on Ingredients

Component	CAS#	% by Wt.
NONYLPHENOL DIETHYLENE TRIAMINE / DETA * XYLENE DIETHYLENETRIAMINE * XYLENE (MIXED ORTHO, META AND PARA ISOMERS) 2,4,6-TRIS <dimethylamino>METHYL PHENOL * ETHYLBENZENE</dimethylamino>	84852153 111-40-0 1330-20-7 111-40-0 1330-20-7 90-72-2 100-41-4	60% TO 65% 15% TO 20% 10% TO 15% 10% TO 15% 10% TO 15% 2% TO 3% 2% TO 3%

4. First Aid Measures

4.1 Description of first aid measures

First-aid measures general: If exposed or concerned, get medical attention/advice. Show this safety data sheet to the doctor in attendance. Wash contaminated clothing before re-use. Never give anything to an unconscious person.

VIKING PAINTS INC

TE-2501 FAST SET CATALYST PART-B FOR USE WITH ALL FAST SET PART-A

Date Printed: 3/17/2016

Date Revised: Page 3 of 8

First-aid measures after inhalation: IF INHALED: Remove to fresh air and keep at rest in a position comfortable for breathing. Get medical attention. If breathing is difficult, supply oxygen. If breathing has stopped, give artificial respiration.

First-aid measures after skin contact: IF ON SKIN (or clothing): Remove affected clothing and wash all exposed skin with water for at least 15 minutes. If irritation develops or persists, get medical attention.

First-aid measures after eye contact: IF IN EYES: Immediately flush with plenty of water for at least 15 minutes. Remove contact lenses if present and easy to do so. If pain, blinking, or irritation develops or persists, get medical attention. Continue rinsing.

First-aid measures after ingestion: IF SWALLOWED: rinse mouth thoroughly. Do not induce vomiting without advice from poison control center or medical professional. Get medical attention if you feel unwell.

4.2 Most important symptoms and effects, both acute and delayed

Symptoms/injuries after inhalation: Harmful if inhaled. Symptoms/injuries after skin contact: Causes skin irritation. May cause an allergic skin reaction.

Symptoms/injuries after eye contact: Causes serious eye irritation. Symptoms/injuries after ingestion: May cause gastrointestinal irritation Chronic symptoms: Suspected of causing cancer.

5. Fire Fighting Measures

5.1 Extinguishing media

Suitable extinguishing media: Carbon dioxide. Dry powder. Foam. Water spray. Water fog.

5.2 Special hazards arising from the substance or mixture

Fire hazard:

Explosion hazard:

Reactivity: Can react vigorously with strong oxidizing agents, mineral acids, & organic bases, especially amines. Also reactions with some curing agents may produce considerable heat, runaway cure reactions may char & decompose resin system.

5.3 Advice for firefighters

Firefighting instructions: Use cold water spray to cool fire-exposed containers to minimize risk of rupture. Fight fire with normal precautions from a reasonable distance. Do not dispose of fire-fighting water in the environment. Exercise caution when fighting any chemical fire.

Protection during firefighting: Do not enter fire area without proper protective equipment, including respiratory protection. Self-contained breathing apparatus.

VIKING PAINTS INC

TE-2501 FAST SET CATALYST PART-B FOR USE WITH ALL FAST SET PART-A

Date Printed: 3/17/2016

Date Revised: Page 4 of 8

6. Accidental Release Measures

6.1 Personal precautions, protective equipment and emergency procedures

General measures: Evacuate area. Ventilate area. Keep upwind. Spill should be handled by trained clean-up crews properly equipped with respiratory equipment and full chemical protective gear (see Section 8).

6.1.1 For non-emergency personnel

Protective equipment: Wear Protective equipment as described in Section 8.

Emergency procedures: Evacuate unnecessary personnel.

6.1.2 For emergency responders

Protective equipment: Wear suitable protective clothing, gloves and eye or face protection. Approved supplied-air respirator, in case of emergency.

6.2 Environmental precautions

Avoid release to the environment. Prevent entry to sewers and public waters. Notify authorities if liquid enters sewers or public waters.

6.3 Methods material for containment and cleaning up

For containment: Contain any spills with dikes or absorbents to prevent migration and entry into sewers or streams.

Methods for cleaning up: Eliminate ignition sources. Wear suitable protective clothing. Ventilate area. Soak up spills with inert solids, such as clay or diatomaceous earth as soon as possible. Place in a suitable container for disposal in accordance with the waste regulations (see Section 13).

7. Handling and Storage

7.1 Precautions for safe handling

Precautions for safe handling: Do not handle until all safety precautions have been read and understood. Wear personal protective equipment. Do not breathe vapor/mist. Avoid contact with skin, eyes and clothing. Keep away from sources of ignition - No smoking. Wash hands and other exposed areas with mild soap and water before eating, drinking or smoking and when leaving work.

7.2 Conditions for safe storage, including any incompatibilities

Storage conditions: Store in a dry, cool and well-ventilated place. Keep container tightly closed. Ground and bond all transfer and storage equipment. Keep away from ignition sources

Storage temperature: Do not store above 49°C (120°F)

8. Exposure Controls/Personal Protection

8.1 Control parameters		
NONYLPHENOL osha pel: n/e, acgih tlv: n/e, mfg's.: n/e	84852153	60% TO 65%
DIETHYLENE TRIAMINE / DETA OSHA PEL: 1 PPM SKIN, ACGIH TLV: 1 PPM SKIN, MFG'S.: N/A	111-40-0	15% TO 20%
* XYLENE OSHA PELL=100PPM	1330-20-7	10% TO 15%
ACGIH=100PPM; STEL=150PPM		
DIETHYLENETRIAMINE OSHA: PEL/TWA 1-PPM ACGIH: TLV/TWA 1-PPM (SKIN)	111-40-0	10% TO 15%

VIKING PAINTS INC

TE-2501 FAST SET CATALYST PART-B FOR USE WITH ALL FAST SET PART-A

Date Printed: 3/17/2016

Date Revised: Page 5 of 8

* XYLENE (MIXED ORTHOSHA PEL/TWA: 100 PPM	HO, META AND PARA ISOMERS) OSHA PEL/STEL: 150 PPM	1330-20-7	10% TO 15%
ACGIH TLV/TWA: 100 PPM	ACGIH TLV/STEL: 150 PPM		
LD50 ORAL: 4.3 G/KG (RAT)	LD50 DERMAL: 3.95 ML/KG (RABBIT)		
LC50 INHALATION: 5000 PPM/4H ((RAT)		
SARA HEALTH ASSESSMENT RANK 72			
2,4,6-TRIS <dimethyla acgih="" e,="" e,<="" n="" osha="" pel:="" td="" tlv:=""><td></td><td>90-72-2</td><td>2% TO 3%</td></dimethyla>		90-72-2	2% TO 3%

100-41-4 2% TO 3%

* ETHYLBENZENE
OSHA PEL/TWA: 100PPM OSHA PEL/STEL: 125PPM
ACGIH TLV/TWA: 100PPM ACGIH TLV/STEL: 125PPM

LD50 ORAL: 3500 MG/KG (RAT) LD50 DERMAL: 17800 MG/KG (RABBIT)

LC50 INHALATION: LCLO: 400PPM/4H (RAT)

SARA HEALTH ASSESSMENT RANK 69

8.2 Exposure controls

Appropriate Engineering Controls:

Provide adequate general and local exhaust ventilation. Use process enclosures, local exhaust ventilation, or other engineering controls to control airborne levels below recommended exposure limits. Use explosion-proof equipment with flammable materials. Ensure adequate ventilation, especially in confined areas.

Personal Protective Equipment:

Gloves. Protective goggles. Protective clothing.

Hand protection

Use gloves chemically resistant to this material when prolonged or repeated contact could occur. Gloves should be classified under Standard EN 374 or ASTM F1296. Suggested glove materials are: Neoprene, Nitrile/butadiene rubber, Polyethylene, Ethyl vinyl alcohol laminate, PVC or vinyl. Suitable gloves for this specific application can be recommended by the glove supplier.

Eye Protection:

Wear eye protection, including chemical splash goggles and a face shield when possibility exists for eye contact due to spraying liquid or airborne particles.

Skin and body protection: Wear long sleeves, and chemically impervious PPE/coveralls to minimize bodily exposure.

Respiratory protection: Use NIOSH-approved dust/particulate respirator. Where vapor, mist, or dust exceed PELs or other applicable OELs, use NIOSH-approved respiratory protective equipment.

9. Physical and Chemical Properties

На

Boiling Point: 96 deg F - 560 deg F

Melting Point:

N/A

Freezing Point: N/A

Flash Point: 200 F. Method: TCC

```
VIKING PAINTS INC
TE-2501 FAST SET CATALYST PART-B
                                       FOR USE WITH ALL FAST SET PART-A
Date Printed: 3/17/2016
Date Revised:
Page 6 of 8
Explosive Limits:
  Lower Explosive limit: 0
  Upper Explosive limit: 11.9
Vapor Pressure:
-.1
6.7
<1.0
5
7.1
Vapor Density:
Solubility
  Solubility in Water:
Evaporation Rate:
Flammability (solid, gas):
Exposure:
  Upper Exposure Limit: N/A
  Lower Exposure Limit: N/A
Specific Gravity: .944
Q/C spec 'VPE-107-FAST SET
                                          pH' not found.
Odor:
N/A
Odor Threshold:
Appearance::
Transparent green color.
Viscosity:
Partition Coefficient:
Autoignition Temperature:
Decomposition Temperature:
10. Stability and Reactivity
10.1 Reactivity
```

N/A

10.2 Chemical stability

Stable under normal conditions.

10.3 Possiblity of hazardous reactions

VIKING PAINTS INC

TE-2501 FAST SET CATALYST PART-B FOR USE WITH ALL FAST SET PART-A

Date Printed: 3/17/2016

Date Revised: Page 7 of 8

N/A

10.4 Conditions to avoid

Avoid contact with strong oxidizers, bases, metals, metal oxides, hydroxides, amines, and other alkaline materials. Incompatible with cyanides, sulfides, and formaldehyde. Corrodes metal, including steel. Produces heat when diluted with water.

10.5 Incompatible materials

None known

10.6 Hazardous decomposition products

Carbon oxides (CO, CO2). Smoke.

11. Toxicological Information

Acute toxicity: Harmful if inhaled.

Skin Corrosion/irritation: Causes skin irritation.

Serious eye damage/irritation: Causes serious eye irritation.

Respiratory or skin sensitisation: May cause an allergic reaction.

Germ cell mutagenicity: Not classified

Carcinogenicity: Suspected of causing cancer.

Reproductive toxicity: N/A

Specific target organ toxicity (single exposure) N/A

Specific target organ toxicity (repeated exposure) N/A

Aspiration hazard: N/A

12. Ecological Information

No data available

13. Disposal Considerations

Waste Treatment Methods:

Do not discharge to public wastewater systems without permit of pollution control authorities. No discharge to surface waters is allowed without an NPDES permit.

Waste disposal recommendations:

Dispose in a safe manner in accordance with local/national regulations. Do not allow the product to be released into the environment.

14. Transport Information

Domestic (Land, DOT), International (Water, IMO/IMDG), International (Air, ICAO) Road and Rail (ADR/RID), Air (ICAO/IATA), Vessel (IMO/IMDG):

UN Number: UN1789

UN Shipping Name: Paint including paint, lacquer, enamel, stain, shellac

solutions, varnish, polish, liquid filler, and liquid lacquer base

Transport Hazard Class: 8

Packing Group: II

Environmental Hazards:

```
VIKING PAINTS INC
TE-2501 FAST SET CATALYST PART-B
                                        FOR USE WITH ALL FAST SET PART-A
Date Printed: 3/17/2016
Date Revised:
Page 8 of 8
N/A
Marine Pollutant:
Special Precautions for User:
15. Regulatory Information
U.S. Federal Regulations:
All chemical substances in this product are listed in the EPA (Environment
Protection Agency) TSCA (Toxic Substances Control Act) Inventory
OSHA:
CERCLA: SARA Hazard Category:
  Section 313:
  * Indicates chemical(s) subject to the reporting requirements of section 313 of Title III and of 40 CFR 372.
International Regulations:
  Canadian WHMIS:
  Canadian Environmental Protection Act (CEPA):
  EINECS:
  N/A
State Regulations:
  Calfornia Proposition 65
  Eliminate all sources of ignition. Avoid Heat, flames, and sparks.
  U.S. - Massachusetts - Right To Know List
  U.S. - Pennsylvania - Right To Know List
  U.S. - New Jersey - Right To Know List
  Volatile Organic Compounds:
  119.487 g/L
```

16. Other Information

Revision date:

3/17/2016
Prepared By: N/A
Information Contact:
N/A
Manufacturer Disclaimer: